

**OHIO VALLEY ELECTRIC CORPORATION** 

3932 U. S. Route 23 P. O. Box 468 Piketon, Ohio 45661 740-289-7200

WRITER'S DIRECT DIAL NO: 740-897-7768

May 15, 2019

## CERTIFIED MAIL RETURN RECEIPT REQUESTED

Mr. Bruno Pigott, Commissioner Indiana Department of Environmental Management 100 N. Senate Avenue Mail Code 50-01 Indianapolis, IN 46204-2251

Dear Mr. Pigott:

## Re: Indiana-Kentucky Electric Corporation Notification of Initiation of Assessment of Corrective Measures

As required by 40 CFR 257.106(h)(7), the Indiana-Kentucky Electric Corporation (IKEC) is providing notification to the Commissioner (State Director) of the Indiana Department of Environmental Management (IDEM) that an Assessment of Corrective Measures has been initiated for a confirmed Statistically Significant Increase (SSI) of Appendix IV constituent Molybdenum at Clifty Creek Station's Landfill Runoff Collection Pond (LRCP). IDEM was previously notified that SSIs had been confirmed for both the Clifty Creek Station Landfill and LRCP. However, IKEC was able to conduct a successful Alternative Source Demonstration (ASD) for the Clifty Creek Landfill so it will therefore remain in Detection Monitoring.

Upon completion of the Assessment of Corrective measures, IKEC will hold a public meeting to discuss the findings and results at least 30 days prior to selecting and implementing a remedy, as prescribed by 40 CFR 257.96(e).

If you have any questions, or require any additional information, please call me at (740) 897-7768.

Sincerely,

Tim Ful

Tim Fulk Engineer II

TLF:klr